



Fig. 10 Here are a couple of photos of the coil directly after the wrapping was removed. The outer winding has no other wrapping or shield.